

YELLOW
NORMALLY OPEN
TAN
COMMON
ORANGE
NORMALLY CLOSED

SWITCH

WIRING FROM
TOUCH BAR

OPERATION:

- CHECK OPERATION WITH CONTINUITY TESTER OR MULTI-METER AT THE TOUCH BAR WITH POWER OFF.

- ① NORMALLY OPEN CONNECTION: (TAN & YELLOW)
 - LATCH BOLT EXTENDED: COMPLETE CIRCUIT
 - LATCH BOLT DEPRESSED: INCOMPLETE CIRCUIT
- ② NORMALLY CLOSED CONNECTION: (TAN & ORANGE)
 - LATCH BOLT EXTENDED: INCOMPLETE CIRCUIT
 - LATCH BOLT DEPRESSED: COMPLETE CIRCUIT

FIELD WIRING
(BY OTHERS)

POWER TRANSFER HINGE REQ'D.
(BY OTHERS)

5/8 DIA. INTO DOOR
FOR WIRE FEED THRU

HINGE STILE
MACHINING

FOR LOCK STILE MACHINING
AND MOUNTING BRACKET LOCATION
SEE DEVICE TEMPLATE

5/8
5/8

FOR FASTENERS REQ'D.
SEE DEVICE TEMPLATE

HORIZONTAL \bar{C}
SEE DEVICE TEMPLATE

NOTE:

- CONSULT LOCAL CODES TO DETERMINE FIELD WIRING

<i>PRECISION HARDWARE INC.</i>	
38100 JAYKAY DRIVE	ROMULUS MI. 48174-0040
DEVICE SERIES	
LATCH BOLT MONITOR SWITCH	
TEMPLATE NO.	RELEASE DATE
ET-1123-6	5-15-00

.100 SIZE